Common Building Flaws

HEC Technologies had indentified typical design flaws resulting in energy related problems:

- Leakage at rim joist, mud sill and sole plates
- Rooms over garages:
 - a. Air flow through floor insulation
 - b. Unsheathed knees walls (wind washing)
 - c. Frozen pipes
 - d. Long duck runs through unconditioned space
 - e. Insufficient supply or return
 - f. Ductwork in outside walls and sloped ceiling
 - g. Access panels leading to unconditioned space behind knee walls
- Brick cantilevers
- Cantilevered floors and cantilevered floors over porches
- Improper fire stopping and insulation of fireplace chases
- Incomplete air barrier behind shower/tub surround and whirlpools
- 7 Interior soffits tied to attics



BUILDING SCIENCE & THERMAL ACOUSTICAL SOLUTIONS



- 8 Ceiling joist in attics tied into floor house of conditioned space without any blocking
- 9 Unsheathed knee walls and lack of fire blocking at changes in ceiling height
- 10 Air leakage and water intrusion at windows.
- Poorly sealed flu chases and plumbing chases.
- Penetration in ceiling (cans, disappearing stairwells and whole hose fans)
- 13 Ductwork and furnaces in attic
- Main trunk lines located near ridge with long supply drops.
- 15 Hi-lo make up air in furnace rooms
- Us of humidifier in structu4res that already have excessive moisture levels
- 17 Lack of provision for mechanical vntilation.
- Use of vapor retarders designed to keep moisture out that actually prevent drying.

20604 Burl Court • Joliet, IL 60433

815-723-1700 info@hectechnologies.com www.hectechnologies.com